Figure 3.3-1 Quarry Components





Figure 3.3-2 Mining Process



Not to Scale



Figure 3.3-3 Quarry Conveyor Circuit

